




TIG300CG

Top Features

- ❖ High current range of 300 amps highly fits for the industrial welding
- ❖ MMA welding current 240 A provides the ability to weld 4.0 electrode
- ❖ Convenient digital operational interface
- ❖ Energy saving and high efficiency
- ❖ Overheat, over-current and over-voltage detection, anti-shock and anti-sticking functions
- ❖ IP21S classification to ensure reliability in harsh and demanding environmental conditions

<i>Technical</i>	<i>Parameters</i>	<i>Technical</i>	<i>Parameters</i>
Input Power	380V(±15%)/3Ph/50HZ/60HZ	Efficiency (%)	85
Rated input current (A)	7.5	Power factor	0.93
Rated Output Current /Voltage/Duty Cycle	10-300A/20V/60%	Insulation grade	F
MMA current (A)	10-240	Housing protection grade	IP21S
No-load voltage (V)	60	Net Weight (kg)	10.46
No-load loss (W)	80	Dimensions H×W×D (mm)	433 x 219 x 351



<i>Function description</i>			
1	MMA	9	Positive output terminal
2	TIG indicator	10	Torch control socket
3	MMA indicator	11	Negative output
4	Digital ammeter	12	Torch interface
5	protection lamp	13	Air intake
6	Post gas adjust knob	14	Power switch
7	Thrust regulating knob	15	Earth connecting screw
8	Welding current adjustment	16	Input power line terminal block

ACCESSORY DRAWING




TIG Torch



Electrode holder with cable



Earth clamp with cable



Connector assembly way



Internal hexagonal wrench

INSTALLATION INSTRUCTION

Long connecting cable can affect the ARC start character and stability of welding performance, so please use the recommended cable length, and in order to reducing the voltage down, please use the large cable face:

1. Please use at least 6mm² cable to connect the welder to the earth.
 2. Please make sure the power supply is right match for the welder and install the torch, earth clamp according to the right instruction;
 - 1) Using the MMA function, please connect the earth clamp and electrode holder according to the nature of electrode, and tighten the connector.
 - 2) Using the TIG function, please following the installation instruction to install the the torch and tighten it.
 3. For the earth clamp, please let the connector connect to "+", and the other side connect to the workpiece.
 4. Before using the welder, please check the cable is right connected as the following picture and tighten them.
 5. Please pay attention to polarity, since there are two connecting method for MMA process. ① positive pole connecting method, earth clamp connect to "-" and electrode holder connect to "+"; ② negative pole connecting method, earth clamp connect of "+" and electrode holder connect to "-".
- Please noted that which connecting way would be used is up to the workpiece processing requirement, if using the wrong connecting way, it will occur some phenomenon.

